

This MSDS complies with OSHA's Hazard Communication Standard CFR 1910.1200 and OSHA Form 174.

N/A SIGNIFIES NON-APPLICABLE

IDENTITY AND SUPPLIERS INFORMATION

PRODUCT NAME: **ETERNABOND GRAY**
RD954, RD955, RD956, RD957

CHEMICAL FAMILY: Polyolefin and Synthetic Elastomer

GENERIC NAME: FORMULA: PROPRIETARY

SUPPLIER'S NAME: GENERAL PRODUCTS & SUPPLY, INC.

PHONE NUMBER: (800) 548-2080

SUPPLIER'S ADDRESS: 101 TECHNOLOGY LANE
EXPORT, PA 15632

EMERGENCY NO.: (847) 540-0600

PROPER SHIPPING NAME:

NFPA HAZARDOUS MATERIALS IDENTIFICATION SYSTEM	RATING
HEALTH	0
FLAMMABILITY	1
REACTIVITY	0
MAX PERSONAL PROTECTION	

SECTION 1 - INGREDIENT IDENTIFICATION AND INFORMATION

CHEMICAL NAME	CARC.	CAS NO.	WT %	SARA III	PEL	TWA-TLV	STEL-TLV
None							

SECTION 2 - PHYSICAL/CHEMICAL PROPERTIES

BOILING POINT: N/A
VAPOR PRESSURE: (mm Hg) N/A
VAPOR DENSITY: N/A
SOLUBILITY IN WATER: Insoluble
SPECIFIC GRAVITY: 1.04 (adhesive)
pH RANGE: N/A
EVAPORATION RATE: (Ether=1) N/A
PHYSICAL DESCRIPTION: Gray and white tapes

SECTION 3 - FIRE/EXPLOSION HAZARD DATA

FLASH POINT: 450°F COC
FLAMMABILITY LIMITS: N/A
EXTINGUISHER MEDIA: Carbon dioxide, dry chemical, foam, water fog, and water spray
SPECIAL FIRE FIGHTING PROCEDURES: Use water to cool fire exposed surfaces and to protect personnel.
UNUSUAL FIRE/EXP. HAZARDS: Toxic gases will form upon combustion.

SECTION 4 - REACTIVITY HAZARD DATA

STABILITY: Stable
HAZARDOUS POLYMERIZATION: Flammable hydrocarbons
INCOMPATIBILITY: Avoid contact with strong oxidizing agents
CONDITIONS TO AVOID: Overheating
HAZARDOUS DECOMPOSITION PRODUCTS: Will not occur

SECTION 5 - HEALTH HAZARD DATA AND FIRST AID

ACUTE EFFECTS:

SKIN: N/A
EYES: N/A
INHALATION: N/A
INGESTION: Acute oral LD50 is greater than 10g/kg

FIRST AID PROCEDURES:

SKIN: Remove with waterless hand cleaner
EYES: Flush with water
INHALATION: N/A
INGESTION: Contact a physician

SECTION 6 - CONTROL AND PROTECTIVE MEASURES

RESPIRATORY PROTECTION: N/A
PROTECTIVE GLOVES: N/A
EYE PROTECTION: Chemical goggles
VENTILATION REQUIREMENTS: N/A

SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IF MATERIAL IS SPILLED OR RELEASED: Sweep up.
WASTE DISPOSAL METHODS: Dispose of in accordance with Federal, State and local regulations.
PRECAUTIONS IN HANDLING AND STORAGE: Do not store near flame, heat or strong oxidizing agents.

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without any warranty or guarantee of any kind.